

To: 13038776160@icmms1.sun5.lightsurf.net[13038776160@icmms1.sun5.lightsurf.net];
13038861635@icmms1.sun5.lightsurf.net[13038861635@icmms1.sun5.lightsurf.net];
13032531659@icmms1.sun5.lightsurf.net[13032531659@icmms1.sun5.lightsurf.net];
17204139190@icmms1.sun5.lightsurf.net[17204139190@icmms1.sun5.lightsurf.net];
13038081738@icmms1.sun5.lightsurf.net[13038081738@icmms1.sun5.lightsurf.net]; Christenson,
Dave[Christenson.Dave@epa.gov];
17204419961@icmms1.sun5.lightsurf.net[17204419961@icmms1.sun5.lightsurf.net]
From: 3034086838@plspictures.com
Sent: Thur 8/13/2015 1:09:47 PM

Sent from my mobile.

LOW urgency, private well sampling status, Most but not all of the info below is in the Gold King Mine Viewer / SADIE. Response to date through Wednesday evening:

~280 sampling requests recieved through call center,

~80 samples collected

~15 raw sample results (NOT validated), validation completion ~7 pm tonight

~20 additional well water raw results expected mid morning today, validation anticipated mid day Friday.